

BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-1404</i>	LOCATION <i>2314-16th St.</i>
DATE <i>8/16/45</i>	PURPOSE <i>Raise dwlg. remodel for apart. over</i>
ZONE	OWNER <i>John E. Jr. & Frank Mosa</i>
	ARCH'T.
	CONTR. <i>Owner</i>

VAL. <i>10,000</i>	STORIES <i>2</i>	ROOMS	APTS.	SIZE
--------------------	---------------------	-------	-------	------

LIGHT SHAFTS	<i>10/11</i>	ELEVATOR SHAFTS
VENT SHAFTS		BOILER ROOMS
OWNER'S INSPECTOR		SPRINKLER SYSTEM
LATH		GAS VENTS
FIRE ESCAPES		CHIMNEYS
STAND PIPES		SKYLIGHTS

DATE	CONDITION OF WORK—REMARKS
	<p data-bbox="315 857 441 896">COMPLETE AND O. K.</p> <p data-bbox="1127 875 1260 896">INSPECTOR</p>