

*5-31-7-15-60*

**BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD**

*350.00*

*Et. 30*

**TYPE BUILDINGS**

*E.L.P. Per. #12*

<b>PERMIT NO.</b>			
<i>E-1356</i>	<b>LOCATION</b>	<i>1226 - 27th Avenue</i>	<i>A-3</i>
<b>DATE</b>	<b>PURPOSE</b>	<i>Const. Dwelling &amp; carport</i>	
<i>Jun 21-63</i>	<b>OWNER</b>	<i>Joseph L. Chau 732 3rd Avenue</i>	
<b>ZONE</b>	<b>ARCH'T</b>		
<i>R-1</i>	<b>CONT'R</b>	<i>Owner GI 2-2059</i>	

<b>VAL.</b>	<b>STORIES</b>	<b>ROOMS</b>	<b>APTS.</b>	<b>100-carport SIZE</b>
<i>\$16,700.</i>	<i>1</i>			<i>1,813 sq. ft.</i>

<b>INSP.</b>	<b>DATE</b>	<b>BLDG. TYPE</b>	<b>OCCUPANCY GROUP</b>	<b>PHONE (O) (C)</b>
<b>FORM</b>	<i>7-11-63</i>	<i>Basement</i>		
<b>JOIST</b>	<i>7-24-63</i>	<i>Framing</i>		
<b>FRAME</b>	<i>9-26-63</i>	<i>Roofing</i>		
<b>SHEET ROCK</b>	<i>10-31-63</i>	<i>Exterior</i>		
<b>FINAL</b>	<i>3-24-64</i>	<i>O. Hammond</i>		

DATE	SPECIAL CONDITIONS OF WORK — REMARKS
7-10-63	PT 4 matches (old) mudills
	not placed: <i>Dimensions</i>
8-10-64	PT (replace) not finished <i>Dimensions</i>
	<p>COMPLETE AND OK</p> <p style="text-align: right;">INSPECTOR</p>