

| | | | | | | |
|----------------------|----------|--|-------|------------------|-----------------------------|-----------------------------|
| Lot #105 | | BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD | | | | \$26.00 |
| Carella Gardens #8 | | TYPE BUILDINGS | | # 86 26 93 | # 621 223-226 622-627 | |
| PERMIT NO. D-9137 | LOCATION | 7533 - 19th Street | | | A-5 | |
| DATE Jul-20-61 | PURPOSE | Const. dwelling & gar. Plan 7X-F | | | | |
| ZONE R-1 | OWNER | Reed Const. Co. 920-9th Street | | | | |
| | ARCH'T | | | | | |
| | CONT'R | George W. Reed | Same | GI 1-4941 | | |
| VAL. \$8,700. | STORIES | 1 | ROOMS | 6 | APTS. | 336-gar. SIZE 924 sq.ft. |
| INSP. | DATE | INSPECTOR | | | | |
| FORM | 8-3-61 | James | | | | |
| JOIST | 8-15-61 | Berry | | | | |
| FRAME | 9-8-61 | Barbato | | | | |
| LATH | 9-15-61 | Berry | | | | |
| FINAL | 3-9-62 | M. Callaway | | | | |

| DATE | SPECIAL CONDITIONS OF WORK—REMARKS |
|----------|---|
| 9-14-61 | PT SR INT. study, finished Jones |
| 10-19-61 | PT SR. Bar drawing between |
| | |
| | |
| | |
| | |
| | |
| | |
| | <p data-bbox="301 823 441 870">COMPLETE AND OK</p> <p data-bbox="1155 844 1295 870">INSPECTOR</p> |