

BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-2467</i>	LOCATION <i>2984 — 35th St.</i>
DATE <i>2/15/39</i>	PURPOSE <i>Remodel interior restaurant</i>
ZONE	OWNER <i>H. C. Mudday</i>
	ARCH'T.
	CON'T'R. <i>Quinn</i>

VAL. <i>25000</i>	STORIES <i>1</i>	ROOMS	APTS.	SIZE
-------------------	---------------------	-------	-------	------

LIGHT SHAFTS		ELEVATOR SHAFTS	
VENT SHAFTS		BOILER ROOMS	
OWNER'S INSPECTOR		SPRINKLER SYSTEM	
LATH		GAS VENTS	
FIRE ESCAPES		CHIMNEYS	
STAND PIPES		SKYLIGHTS	

DATE	CONDITION OF WORK-REMARKS

COMPLETE
AND O. K.

INSPECTOR