

## BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

## TYPE BUILDINGS

PERMIT NO. <i>B-13598</i>	LOCATION <i>100 - 40<sup>th</sup> St.</i>
DATE <i>7/3/45</i>	PURPOSE <i>Erect new dwlg no garage</i>
ZONE	OWNER <i>Tray Grayhart</i>
	ARCH'T.
	CONTR. <i>Vernon Cox</i>

VAL. <i>4700<sup>00</sup></i>	STORIES <i>1</i>	ROOMS <i>5</i>	APTS.	SIZE
-------------------------------	---------------------	-------------------	-------	------

LIGHT SHAFTS		ELEVATOR SHAFTS	<i>Area 9700<sup>1</sup></i>
VENT SHAFTS		BOILER ROOMS	
OWNER'S INSPECTOR		SPRINKLER SYSTEM	
LATH		GAS VENTS	
FIRE ESCAPES		CHIMNEYS	
STAND PIPES		SKYLIGHTS	

DATE	CONDITION OF WORK—REMARKS
7/12/25	25' Set Back 1 <sup>ST</sup> / ASP. Forms for New Drive <sup>OK</sup> R.H. Campbell
8/13/25	2 <sup>ND</sup> / ASP. Forms " " " <sup>OK</sup> R.H. Campbell

COMPLETE  
AND O. K.

INSPECTOR