

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-4709</i>	LOCATION <i>5424-H St</i>
DATE <i>11/20/40</i>	PURPOSE <i>New dwg</i>
ZONE <i>or-fam</i>	OWNER <i>Ester MacLaughlin</i>
	ARCH'T. <i>J. G. Hecker</i>
	CONTR. <i>J. G. Hecker</i>
VAL <i>4000</i>	STORIES <i>10</i>
	ROOMS <i>5</i>
	APTS.
	SIZE

LIGHT SHAFTS		ELEVATOR SHAFTS	
VENT SHAFTS		BOILER ROOMS	<i>area</i>
OWNER'S INSPECTOR		SPRINKLER SYSTEM	<i>950 ft</i>
LATH.		GAS VENTS	<i>@ 352</i>
FIRE ESCAPES		CHIMNEYS	
STAND PIPES		SKYLIGHTS	

DATE	CONDITION OF WORK—REMARKS	
2/5-39	1 <sup>5</sup>	Susp Forms of Pictor
3/26-40	2	" frame " Pictor
3/5-40	3	" " " Pictor
4/23-40	3	" " " Pictor

COMPLETE  
AND O. K.

INSPECTOR