

R 238 F190

**BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD \$13.00**

**TYPE BUILDINGS**

PERMIT NO. <b>G-374</b>	LOCATION	<b>2520 - 48th Avenue A-4 (41)</b>		
DATE <b>May-15-68</b>	PURPOSE	<b>Const. detached garage on rear lot.</b>		
ZONE <b>R-1</b>	OWNER	<b>Alfonso M. Lopez 2520 - 48th Ave.</b>		
	ARCH'T			
	CONTR	<b>Owner</b>	<b>Same</b>	<b>422-1426</b>

VAL.	<b>\$1,100.</b>	STORIES	ROOMS	APTS.	SIZE
					<b>450 sq.ft.</b>

INSP.	DATE	BLDG. TYPE	OCCUPANCY GROUP	PHONE (O) (C)

FORM	<i>55460 Calloway</i>			
------	-----------------------	--	--	--

JOIST				
-------	--	--	--	--

FRAME	<i>B-26-65 Lido</i>			
-------	---------------------	--	--	--

SHEET ROCK				
------------	--	--	--	--

FINAL	<i>81369 J Barbato</i>			
-------	------------------------	--	--	--

DATE	SPECIAL CONDITIONS OF WORK — REMARKS
P-22-68	St Edward plywood not at job no plans on job. Traces mold & large knots missing. (Chapman)
	COMPLETE AND OK

INSPECTOR