

BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

| | |
|------------------------------|--|
| PERMIT NO. <i>B-10,66</i> | LOCATION <i>3540 - 38th St.</i> |
| DATE <i>9/3/42</i> | PURPOSE <i>Repairs to dwlg. fire loss</i> |
| ZONE | OWNER <i>J. Taylor, J.</i> |
| | ARCH'T. <i>Chas Vanera</i> |
| | CONTR. |

| | | | | |
|------------------------------|---------|-------|-------|------|
| VAL. <i>500⁰⁰</i> | STORIES | ROOMS | APTS. | SIZE |
|------------------------------|---------|-------|-------|------|

| | | | |
|-------------------|--|------------------|--|
| LIGHT SHAFTS | | ELEVATOR SHAFTS | |
| VENT SHAFTS | | BOILER ROOMS | |
| OWNER'S INSPECTOR | | SPRINKLER SYSTEM | |
| LATH | | GAS VENTS | |
| FIRE ESCAPES | | CHIMNEYS | |
| STAND PIPES | | SKYLIGHTS | |

| DATE | CONDITION OF WORK—REMARKS |
|-----------------------|--|
| 9/3/42 | Made Partial Snap of Dwg recently damaged by fire. A W Campbell |
| | |
| | |
| | |
| | |
| | |
| | |
| COMPLETE AND O. K. | INSPECTOR |