

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

| | |
|-----------------------------|-------------------------------------------------|
| PERMIT NO. <i>B-3514</i> | LOCATION <i>2521-51st Street.</i> |
| DATE <i>4/26/39</i> | PURPOSE <i>Remodel dwlg.</i> |
| ZONE <i>-</i> | OWNER <i>L. G. Miller</i> |
| | ARCH'T. <i>Robert Hill</i> |
| | CONT'R. <i>Robert Hill</i> |

| | | | | |
|-------------------------------|---------|-------|-------|------|
| VAL. <i>1500⁰⁰</i> | STORIES | ROOMS | APTS. | SIZE |
|-------------------------------|---------|-------|-------|------|

| | | | |
|-------------------|--|------------------|--|
| LIGHT SHAFTS | | ELEVATOR SHAFTS | |
| VENT SHAFTS | | BOILER ROOMS | |
| OWNER'S INSPECTOR | | SPRINKLER SYSTEM | |
| LATH | | GAS VENTS | |
| FIRE ESCAPES | | CHIMNEYS | |
| STAND PIPES | | SKYLIGHTS | |

| DATE | CONDITION OF WORK—REMARKS |
|-------------|----------------------------------|
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | COMPLETE AND O. K. |

INSPECTOR