

BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>No CHARGE</i>	LOCATION <i>1015-20th St</i>			
DATE <i>Sept 21 1931</i>	PURPOSE <i>Install 6 Patent Churnney on metal Bracket on rear wall</i>			
ZONE <i>General Commercial</i>	OWNER <i>MILLER & SHERIDAN</i>			
	ARCH'T			
	CONT-R <i>OWNER</i>			
VAL. <i>25⁰⁰</i>	STORIES <i>2</i>	ROOMS	APTS.	SIZE

Light Shafts		Elevator Shafts	
Vent Shafts		Boiler Rooms	
Owner's Inspector		Sprinkler System	
Lath		Gas Vents	
Fire Escapes		Chimneys	
Stand Pipes		Skylights	

DATE	CONDITION OF WORK-REMARKS
9/21/31	<p>Made trip of location & proposed 6" Portland Chimney on rear wall of South Apt on 2nd floor for Circulation Heater T.C. Thimble through Hall with Ventilated Flange around thimble.</p>
	<p>OK A.W. Campbell</p>
	<p>COMPLETE AND O.K.</p> <p style="text-align: right;">INSPECTOR</p>

