

## BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

## TYPE BUILDINGS

PERMIT NO. <i>A-1511</i>	LOCATION <i>2315-23<sup>1/2</sup> St.</i>
DATE <i>3/28/34</i>	PURPOSE <i>Re-roof dwell cedar shingles -</i>
ZONE	OWNER <i>Byrne</i>
	ARCH'T <i>J. C. Ruby -</i>
	CONT-R

PHONES

VAL.

*17000*

STORIES

ROOMS

APTS.

SIZE

Light Shafts		Elevator Shafts	
Vent Shafts		Boiler Rooms	
Owner's Inspector		Sprinkler System	
Lath		Gas Vents	
Fire Escapes		Chimneys	
Stand Pipes		Skylights	

DATE	CONDITION OF WORK--REMARKS
7/23/32	Gave carpenter Miss Mc Clelland Permit for cleaning Screens to Windows in opening OK A.W. Campbell
	COMPLETE AND O. K. <span style="float: right;">INSPECTOR</span>