

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <b>B-10,398</b>	LOCATION <b>639-55<sup>th</sup> St.</b>
DATE <b>5/22/42</b>	PURPOSE <b>Erect new dwlg. for</b>
ZONE	OWNER <b>John Fernandez</b>
	ARCH'T.
	CONTR. <b>Owner</b>

VAL. <b>3000<sup>00</sup></b>	STORIES <b>1</b>	ROOMS <b>4</b>	APTS.	SIZE
-------------------------------	---------------------	-------------------	-------	------

LIGHT SHAFTS		ELEVATOR SHAFTS	<b>Area</b>
VENT SHAFTS		BOILER ROOMS	
OWNER'S INSPECTOR		SPRINKLER SYSTEM	<b>750<sup>00</sup></b>
LATH		GAS VENTS	<b>@ 350</b>
FIRE ESCAPES		CHIMNEYS	
STAND PIPES		SKYLIGHTS	

DATE	CONDITION OF WORK-REMARKS	
1/2-42	1	Lump forms at center
2-10-42	2	" Frame at center
4/20 42	3	" Lark & Edge Point
7/10 42	4	" Tracked at center

COMPLETE  
AND O. K.

INSPECTOR