

BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-5333</i>	LOCATION <i>3809 - 39th Street</i>
DATE <i>4/18/40</i>	PURPOSE <i>New dwls</i>
ZONE	OWNER <i>C. C. Ruby</i>
	ARCH'T.
	CON'TR. <i>C. C. Ruby</i>

VAL <i>4800⁰⁰</i>	STORIES <i>1</i>	ROOMS <i>5</i>	APTS.	SIZE
------------------------------	---------------------	-------------------	-------	------

LIGHT SHAFTS		ELEVATOR SHAFTS	<i>area</i>
VENT SHAFTS		BOILER ROOMS	<i>950^{sq}'</i>
OWNER'S INSPECTOR		SPRINKLER SYSTEM	<i>@ 300</i>
LATH		GAS VENTS	
FIRE ESCAPES		CHIMNEYS	
STAND PIPES		SKYLIGHTS	

DATE	CONDITION OF WORK--REMARKS
4/19-40	15' Camp Formed at Pelter
5/3/41	" " " " Formed at Pelter
	<p>COMPLETE AND O. K.</p> <p style="text-align: right;">INSPECTOR</p>