

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT No. <i>A-2409</i>	LOCATION <i>3328 - 9th Ave</i>
DATE <i>1/4/35</i>	PURPOSE <i>Re-model rear of dwell.</i>
ZONE <i>2-Fam</i>	OWNER <i>C. H. Watson</i>
	ARCH'T
	CONT'R <i>Querner</i>
VAL. <i>500⁰⁰</i>	STORIES
	ROOMS
	APTS.
	SIZE

Light Shafts		Elevator Shafts	
Vent Shafts		Boiler Rooms	
Owner's Inspector		Sprinkler System	
Lath		Gas Vents	
Fire Escapes		Chimneys	
Stand Pipes		Skylights	

DATE	CONDITION OF WORK-REMARKS
1/15/35	Make Jack. of Forms In Addition to
	rear of Driv. with excavated extensions
	to basement with concrete steps to same.
	Below Slab on Rock Form O.K. - W. Campbell
	COMPLETE AND O. K. INSPECTOR