

BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <b>8747</b>	LOCATION <b>2816 22<sup>nd</sup> St.</b>
DATE <b>10/15/31</b>	PURPOSE <b>Repairs <sup>acct</sup> Termite</b>
ZONE <b>1st</b>	OWNER <b>Mrs Leo Brecken</b>
	ARCH'T
	CONT-R <b>Capital Termite Control</b>
VAL. <b>100 -</b>	STORIES
	ROOMS
	APTS.
	SIZE

Light Shafts		Elevator Shafts	
Vent Shafts		Doller Rooms	
Owner's Inspector		Sprinkler System	
Lath		Gas Vents	
Fire Escapes		Chimneys	
Stand Pipes		Skylights	

DATE	CONDITION OF WORK-REMARKS
7/31/91	Finished work P.H. [unclear]
	COMPLETE AND O.K. <span style="float: right;">INSPECTOR</span>

