

91507526-610

E $\frac{1}{2}$  of the BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD \$259.50

N.  $\frac{1}{2}$  of Lot 7 & 8, Blk. TYPE BUILDINGS  
 bounded by 14th, 15th, R. & S. *14th 15th R. & S. 14th 15th R. & S.*

PERMIT NO. <b>E-8090</b>		LOCATION <b>1431 - S Street</b>		A-2	
DATE <b>Aug-11-64</b>		PURPOSE <b>Const. office building</b>			
ZONE <b>M-1</b>		OWNER <b>Palm Iron Works</b>		Same	
		ARCH'T <b>Cox-Liske-Assoc. 4000-El Camino</b>			
		CONTR <b>Holdener Const. 2608 - R Street</b>			
VAL. <b>\$139,600.</b>		STORIES <b>2</b>	ROOMS	APTS.	<b>2,940 sq. ft.</b>
					<b>4,200 sq. ft.</b>
INSP.	DATE	BLDG. TYPE <b>V-no hr.</b>		OCCUPANCY GROUP <b>F-2</b>	PHONE (O) (C) <b>GL 6-3809</b>
FORM					
JOIST					
FRAME	<i>12-30-61</i>	<i>Hagmann</i>			
SHEET ROCK	<i>1-22-65</i>	<i>Dansen</i>			
FINAL	<i>3-23-65</i>	<i>Dann Miller</i>			
		<i>Int Conn</i>			

DATE	SPECIAL CONDITIONS OF WORK — REMARKS
8-19-64	Footings in basement - OK - Hammors
8-21-64	1st floor footings O.K. Fuller
9-24-64	Basement Slab - OK Hammors
9-28-64	OK portion of Slab S.E. corner
10-20-64	4-8-138 OK - P. Hammors
11-25-64	OK Roof & Drip M. Caplow
12-10-64	PT. not ready for Drip Hammors
12-16-64	Frame OK in basement + second floor only - Hammors
12-18-64	OK Exterior Satch J. Bickel
1/4/64	S. ROCK OK BASEMENT AREA - EXCEPT STAIRS AND PIPE COLUMN. Piles
1-15-65	PT. Question to "Bacheloroid - Backing in stair Larson
1-18-65	OK S. ROCK. 2ND FLOOR. (Piles)
1-20-65	OK S/R portion sign on plan - Larson
3-12-65	PT. Strip parking - Post address & finish stairs Larson
	COMPLETE AND OK

INSPECTOR