

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-4057</i>	LOCATION <i>5309 - 5th Street</i>
DATE <i>10/18/39</i>	PURPOSE <i>Erect new dwg. gar</i>
ZONE <i>v-farm</i>	OWNER <i>Geo. Tayer</i>
	ARCH'T.
	CONTR. <i>Fred Miller</i>

VAL. <i>2000</i>	STORIES <i>1</i>	ROOMS <i>4</i>	APTS.	SIZE
------------------	---------------------	-------------------	-------	------

LIGHT SHAFTS	ELEVATOR SHAFTS	<i>Area 724^{sq} @ 354</i>
VENT SHAFTS	BOILER ROOMS	
OWNER'S INSPECTOR	SPRINKLER SYSTEM	
LATH	GAS VENTS	
FIRE ESCAPES	CHIMNEYS	
STAND PIPES	SKYLIGHTS	

DATE	CONDITION OF WORK—REMARKS
	<p data-bbox="314 875 450 916">COMPLETE AND O. K.</p> <p data-bbox="1236 896 1388 916">INSPECTOR</p>