

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-5725</i>	LOCATION <i>3517 - 38<sup>th</sup> Street -</i>
DATE <i>6/6/40</i>	PURPOSE <i>New dwls. &amp; garage</i>
ZONE	OWNER <i>Ruth M. Porter -</i>
	ARCH'T.
	CONTR. <i>R. J. Porter -</i>

VAL. <i>3000<sup>00</sup></i>	STORIES <i>4</i>	ROOMS <i>4</i>	APTS.	SIZE
-------------------------------	---------------------	-------------------	-------	------

LIGHT SHAFTS	ELEVATOR SHAFTS	<i>area</i>
VENT SHAFTS	BOILER ROOMS	<i>885<sup>00</sup></i>
OWNER'S INSPECTOR	SPRINKLER SYSTEM	<i>@ 310</i>
LATH	GAS VENTS	
FIRE ESCAPES	CHIMNEYS	
STAND PIPES	SKYLIGHTS	

DATE	CONDITION OF WORK-REMARKS
6/25/40	2 <sup>ND</sup> / NSP. FRAME <sup>OK</sup> R W Campbell
6/28/40	3 <sup>RD</sup> / NSP. INT & EXT LIGHT <sup>OK</sup> R W Campbell
	<p>COMPLETE AND O. K.</p> <p style="text-align: right;">INSPECTOR</p>