

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPES I, II, III, IV, V, VI-BUILDINGS

PERMIT NO.

2999

LOCATION

1014-28

DATE

PURPOSE

Gen Rep

PHONES

OWNER

Street Bldg

ARCH'T

ENGR

On

ISSUED
JUL 19 1928
SACRAMENTO
BUILDING DIVISION

571

STORIES

ROOMS

APTS.

SIZE

Steel Tested by

Elevator Shafts

Cement Tested by

Boller Rooms

Owner's Inspector Rfd. Conc.

Sprinkler System

Fire Escapes

Floor Tests

Stand-pipes



DATE	CONDITION OF WORK—REMARKS
7/10/28	Called at above address. Was informed by the owner Mr. Frost (384) St. that Ed Burke was doing the remodeling, & repairs to bldg. Left word for him to come to office & take out Bldg. Permit.
7/20/28	2 nd H.S.P. Frame Contractor removed wood columns in center supporting 2 nd story, and installed steel H. Column instead. Also repaired 1 st floor. Remodeled 1 st floor for Barber Shop & Post Hall. Did not use street. <i>A. W. Campbell</i>
7/20/28	COMPLETED AND O. K. <i>Allen W. Campbell</i> Inspector