

BUILDING DIVISION--BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <b>9648</b>	LOCATION <i>Service Station at 1324-21<sup>st</sup> St.</i>			
DATE <i>July 8 1932</i>	PURPOSE <i>Build 20'x24' Open Shed Addition To Access To PLO's</i>			
ZONE <i>General Commercial</i>	OWNER <i>MRS P. J. Hahn</i>			
	ARCH'T <i>See Original Permit # 9416</i>			
	CONT-R <i>Owner</i>			
VAL. <i>500<sup>00</sup></i>	STORIES <i>1</i>	ROOMS	APTS.	SIZE

Light Shafts		Elevator Shafts	
Vent Shafts		Boiler Rooms	
Owner's Inspector		Sprinkler System	
Lath		Gas Vents	
Fire Escapes		Chimneys	
Stand Pipes		Skylights	



DATE	CONDITION OF WORK--REMARKS
7/14/32	2 <sup>nd</sup> HSP. Frame for detector to be assembled back of frame 5' from line <sup>or</sup> A. W. Campbell
COMPLETE AND O. K.	INSPECTOR

