

RECORD CARD - BUILDING INSPECTIONS DIVISION - CITY OF SACRAMENTO, CALIFORNIA

PROPERTY PARCEL NO.		JOB ADDRESS		LEGAL DESCRIPTION	
5		3441 JOLA CIRCLE		LOT 143 SOUTHWATE #1	
INSPECTION AREA		CITY LIC. NO.		TITLE AND NAME	
5		HI7-3072		ROBIN CO.	
BUILDING BY		ELECTRICAL BY		GEN. CONTR.	
BARBARO		5/11/67		ELEC. CONTR.	
DATE		PLUMBING BY		PLBG. CONTR.	
DATE		MECHANICAL BY		MECH. CONTR.	
DATE		CERTIFICATE OF OCCUPANCY		ARCH. ENGR.	
ISSUED BY		541 S. TYLER, EL MONTE, CALIF.		OWNER	
DATE		C.I. CASE		HARBOUR HOUSE & GARDEN	
C.S.D.		TOTAL AREA		NO. OF STORIES	
CENSUS TRCT. NO.		1,365 sq. ft.		ROOMS	
EXISTING BLDG'S SAME LOT		AREA 1st FLOOR		TOTAL HEIGHT	
460 GAR.		SPACES		BLDG. LENGTH	
TREES RMVD.		PARK'G REQ.		REAR YARDS	
HOW USED		USE ZONE		SET BACK REQ.	
		R-1		SIDE YARDS	

NATURE OF WORK:- CONST., DWLG., & GAR.

PERMIT NO. S.P.	D-4279	ISSUED BY	
ISSUANCE DATE	12/16/59	PLANS AND APPLICATION	REEL NO. 64
VALUATION	\$ 13,100.	INSPECTION RECORD	REEL NO. 64
R.D.F. FEE	\$	JOB FILE	REEL NO.
S.M.I. FEE	\$	FRAME NO.-	TO
PLAN CK. FEE	\$	169	170
SEWER INCL. FEE	\$	132	148
PERMIT FEE	\$ 38.50	FRAME NO.-	TO
TOTAL FEES	\$	517-1345	

REMARKS AND/OR VARIANCES

Handwritten notes: 517-1345 - [unclear]