

BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-15792</i>	LOCATION <i>3417 - 2 St.</i>
DATE <i>4/2/46</i>	PURPOSE <i>Repairs to interior termite</i>
ZONE	OWNER <i>Cliff Harper</i>
	ARCH'T.
	CON'R. <i>Spray Moore</i>

VAL. <i>783⁰⁰</i>	STORIES	ROOMS	APTS.	SIZE
------------------------------	---------	-------	-------	------

LIGHT SHAFTS		ELEVATOR SHAFTS	
VENT SHAFTS		BOILER ROOMS	
OWNER'S INSPECTOR		SPRINKLER SYSTEM	
LATH		GAS VENTS	
FIRE ESCAPES		CHIMNEYS	
STAND PIPES		SKYLIGHTS	

DATE	CONDITION OF WORK—REMARKS
COMPLETE AND O. K.	INSPECTOR