BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPES I, II, III, IV, V, VI BUILDINGS

PERMIT NO. Mr Cly	LOCATION 1301 — 47" Lot
DATE	PURPOSE R. S. Idzuch — PHONES
	OWNER
ZONE	ARCH'T Park Sheet Metal Wks
	CONT'R 2562 — Beverly Blvd

VAL.	STORIES	ROOMS	APTS.	SIZE

Steel Tested by		Elevator Shafts	
Cement Tested by	1-60 Gal. Tank	Boiler Rooms	3 H.P. 10
Owner's Inspector Rfcd. Conc.		Sprinkler System	
		Floor Tests	
Fire Escapes			
Stand-pipes			

DATE	CONDITION OF WORK—REMARKS
	COMPLETED AND O. K. Inspector

[redacted]