

H/35 7470

BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD

\$5.00

TYPE BUILDINGS

PERMIT NO. <i>E-5944</i>	LOCATION <i>2700 - Portola Way</i> <i>A-2</i>			
DATE <i>Jan 14-64</i>	PURPOSE <i>Repair rot damage to dwlg.</i>			
	OWNER <i>S. Hall</i> <i>Same</i>			
ZONE <i>R-1</i>	ARCH'T <i>GI 81882</i>			
	CON'TR <i>Valley Termite 1617 - 18th St.</i>			
VAL <i>\$200.</i>	STORIES	ROOMS	APTS.	SIZE
INSP.	DATE	BLDG. TYPE	OCCUPANCY GROUP	PHONE (O) (C)
FORM				
JOIST				
FRAME	<i>1-31-64</i>	<i>Aluminum</i>		
SHEET ROCK				
FINAL	<i>1-27-64</i>	<i>J. Pulvato</i>		<i>Int</i>

DATE	SPECIAL CONDITIONS OF WORK — REMARKS
COMPLETE AND OK	INSPECTOR