

*R97 7192 1939*

**BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD \$5.00**

**TYPE BUILDINGS**

|                            |   |             |
|----------------------------|---|-------------|
| PERMIT NO.<br><b>E-816</b> | LOCATION <b>1817 - 44th Street</b>            | <b>A-1</b>  |
| DATE<br><b>Mar. 16-62</b>  | PURPOSE <b>Const. patio roof on dwelling.</b> |             |
|                            | OWNER <b>Mrs. Dora Sanchez</b>                | <b>Same</b> |
| ZONE<br><b>R-1</b>         | ARCH'T <b>GI 2-2023</b>                       |             |
|                            | CONT'R <b>Don Arney 614 - 25th Street</b>     |             |

|                   |         |       |       |                            |
|-------------------|---------|-------|-------|----------------------------|
| VAL <b>\$400.</b> | STORIES | ROOMS | APTS. | SIZE<br><b>210 sq. ft.</b> |
|-------------------|---------|-------|-------|----------------------------|

| INSP.      | DATE           | BLDG. TYPE        | OCCUPANCY GROUP |
|------------|----------------|-------------------|-----------------|
| FORM       | <i>3-23-62</i> | <i>Pills</i>      |                 |
| JOIST      |                |                   |                 |
| FRAME      |                |                   |                 |
| SHEET ROCK |                |                   |                 |
| FINAL      | <i>4/9/62</i>  | <i>Geo. Pills</i> |                 |

| DATE | SPECIAL CONDITIONS OF WORK — REMARKS  |
|------|---|
|      |   |
|      |   |
|      |   |
|      |   |
|      |   |
|      |   |
|      |   |
|      |   |
|      |   |
|      |   |
|      | <p data-bbox="263 964 414 1033"><b>COMPLETE<br/>AND OK</b></p> <p data-bbox="1236 993 1396 1027"><b>INSPECTOR</b></p> |