

②1817536

**BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD** \$5.00

**TYPE BUILDINGS**

<b>PERMIT NO.</b> F-2433		<b>LOCATION</b> 916 - 3rd Avenue		A-2	
<b>DATE</b> Nov 30-65		<b>PURPOSE</b> Const. addn. on det. garage			
		<b>OWNER</b> L. Blucher same			
<b>ZONE</b> R-1		<b>ARCH'T</b>			
		<b>CONTR</b> Guth & Schmudt Const.		2821 - S Street	
<b>VAL.</b> \$500.		<b>STORIES</b>	<b>ROOMS</b>	<b>APTS.</b>	<b>SIZE</b> 36 sq. ft.
<b>INSP.</b>	<b>DATE</b>	<b>BLDG. TYPE</b>	<b>OCCUPANCY GROUP</b>	<b>PHONE (O) (C)</b> 452-4569	
<b>FORM</b>	11-30-65	Permits			
<b>JOIST</b>					
<b>FRAME</b>					
<b>SHEET ROCK</b>					
<b>FINAL</b>	2-10-66				

DATE	SPECIAL CONDITIONS OF WORK — REMARKS
COMPLETE AND OK	INSPECTOR