

*B145 2200*

**BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD \$5.00**

**TYPE BUILDINGS**

<b>PERMIT NO.</b>		<b>LOCATION</b>			
<i>E-7403</i>		<i>4531 - 53rd Street A-2</i>			
<b>DATE.</b>		<b>PURPOSE</b>			
<i>Jun 3-64</i>		<i>Repair termite damage to dwelling</i>			
<b>ZONE</b>		<b>OWNER</b>			
<i>R-1</i>		<i>Phil Ryno 2418 - 26th Street</i>			
		<b>ARCH'T</b>			
		<i>GI 8-1882</i>			
		<b>CONT'R</b>			
		<i>Valley Termite Co. 1617-18th Street</i>			
<b>VAL</b>		<b>STORIES</b>	<b>ROOMS</b>	<b>APTS.</b>	<b>SIZE</b>
<i>\$400.</i>					
<b>INSP.</b>	<b>DATE</b>	<b>BLDG. TYPE</b>		<b>OCCUPANCY GROUP</b>	<b>PHONE (O) (C)</b>
<b>FORM</b>					
<b>JOIST</b>					
<b>FRAME</b>	<i>6-5-64</i>	<i>M. Callaway</i>			
<b>SHEET ROCK</b>					
<b>FINAL</b>	<i>6-16-64</i>	<i>Dana Fuller</i>			

BLDG. INS. DIV. - PHOENIX, ARIZONA  
 FORM 1 - 6-64  
 PRINTED IN ARIZONA

DATE	SPECIAL CONDITIONS OF WORK — REMARKS
	<b>COMPLETE AND OK</b> <span style="float: right;"><b>INSPECTOR</b></span>