

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <b>B-413</b>	LOCATION <b>809-43<sup>rd</sup> St</b>
DATE <b>5/26/38</b>	PURPOSE <b>New dwlg. on</b>
ZONE <b>2-Fam</b>	OWNER <b>Dale Edstrom</b>
	ARCH'T. <b>Safe Milsbaugh</b>
VAL. <b>3500</b>	CON'TR. <b>Safe Milsbaugh</b>
	STORIES <b>1</b>
	ROOMS <b>3</b>
	APTS.
	SIZE

LIGHT SHAFTS		ELEVATOR SHAFTS	<b>1000'</b>
VENT SHAFTS		BOILER ROOMS	
OWNER'S INSPECTOR		SPRINKLER SYSTEM	
LATH		GAS VENTS	
FIRE ESCAPES		CHIMNEYS	
STAND PIPES		SKYLIGHTS	

DATE	CONDITION OF WORK—REMARKS
5/27/38	1st Insp Forms OK Routes
6/9. 38	2 " Frame " Routes
	2 " Park West Routes
8/8=38	4 " Formed & Citywide
	Occupancy Survey Routes

COMPLETE AND O. K.

INSPECTOR