

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-8136-</i>	LOCATION <i>2788—Riverside Bl.</i>			
DATE <i>5/2/41</i>	PURPOSE <i>Reface dwg.</i>			
ZONE	OWNER <i>Charles C. Smith</i>			
	ARCH'T.			
	CONT'R. <i>J. C. Hansen</i>			
VAL. <i>300⁰⁰</i>	STORIES	ROOMS	APTS.	SIZE
LIGHT SHAFTS		ELEVATOR SHAFTS		
VENT SHAFTS		BOILER ROOMS		
OWNER'S INSPECTOR		SPRINKLER SYSTEM		
LATH		GAS VENTS		
FIRE ESCAPES		CHIMNEYS		
STAND PIPES		SKYLIGHTS		

DATE	CONDITION OF WORK-REMARKS
5/2/41	<p>Make dup of remaining old "Kellstone" Plaster in areas of dist. with new Kell paper - 18-gauge. Put in wire and cement Plaster in place ^{OR} R.W. Campbell</p>
	<p>COMPLETE AND O. K.</p> <p style="text-align: right;">INSPECTOR</p>