

BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>8607</i>	LOCATION <i>733 Santa Fe</i>		
DATE <i>9/21/31</i>	PURPOSE <i>add alter - Rep Dr garage</i>		
OWNER <i>Wm</i>	ARCH'T <i>Wm H. Allison</i>		
VAL. <i>2000</i>	CONT-R <i>W H Thompson</i>		
STORIES	ROOMS	APTS.	SIZE

Light Shafts		Elevator Shafts	
Vent Shafts		Boiler Rooms	
Owner's Inspector		Sprinkler System	
Lath		Gas Vents	
Fire Escapes		Chimneys	
Stand Pipes		Skylights	

DATE

CONDITION OF WORK-REMARKS

9/21/31

1ST / ASP. Forms for Addition to Duly, ^{or} R.H. Campbell

COMPLETE
AND O.K.

INSPECTOR

BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>8607</i>	LOCATION <i>733 Santa Fe</i>
DATE <i>9-21-31</i>	PURPOSE <i>Home on Lot Gen. Rep. Pkt. 2, 3, 4, 5</i>
OWNER <i>James</i>	ARCH'T <i>W. H. W. Williams</i>
ZONE <i>James</i>	CONT-R <i>W. H. W. Williams</i>

PHONES

VAL. <i>2000 -</i>	STORIES	ROOMS	APTS.	SIZE
-----------------------	---------	-------	-------	------

Light Shafts		Elevator Shafts	
Vent Shafts		Boiler Rooms	
Owner's Inspector		Sprinkler System	
Lath		Gas Vents	
Fire Escapes		Chimneys	
Stand Pipes		Skylights	

DATE	CONDITION OF WORK-REMARKS
9/21/31	1 ST /NSP. Frame for Addition. ^{OK} H.W. Campbell
10/13/31	2 ND /NSP. Frame for front part. ^{OK} H.W. Campbell
10/19/31	2 ND /NSP. Bal of Frame rear part. ^{OK} H.W. Campbell
10/19/31	3 RD /NSP. EXT LATH in place. ^{OK} H.W. Campbell
10/22/31	3 RD /NSP. INT LATH (new part) ^{OK} H.W. Campbell
	<p data-bbox="364 835 515 881">COMPLETE AND O.K.</p> <p data-bbox="1135 855 1294 881">INSPECTOR</p>