

**BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD**

**TYPE VII BUILDINGS**

<b>PERMIT NO.</b> <i>7420</i>	<b>LOCATION</b> <i>1335-57<sup>TH</sup> STREET</i>		
<b>DATE</b> <i>Dec. 4, 1930</i>	<b>PURPOSE</b> <i>Stucco Plaster Ext. of Dwg with Cement Plaster &amp; Mbr. Repair</i>	<b>ROOMS</b>	<b>APTS.</b> <i>to parties</i>
	<b>OWNER</b> <i>F. BANDUCCI</i>	<b>PHONE</b>	
<b>ZONE</b> <i>2-Family</i>	<b>ARCH'T</b>		
	<b>CONT'R</b> <i>OWNER</i>		
<b>VAL.</b> <i>200<sup>00</sup></i>	<b>STORIES</b> <i>1</i>	<b>SIZE</b>	

FOUNDATION	STORY	BSMT	1	2	3	ROOF		
<b>EX WALL</b>	<b>Joists</b>						<b>Chimneys</b>	<b>Cement Tests</b>
	<b>Beams and Girders</b>						<b>Fire Place</b>	
<b>Int Wall</b>	<b>Studs and Columns</b>						<b>Gas Water Heater</b>	
	<b>Bridging Fire Stops</b>						<b>Heater Closet</b>	
<b>Piers</b>	<b>Fire Escape Stand Pipes</b>						<b>Furnace</b>	<b>Window Courts</b>
	<b>Metal Lath</b>						<b>Boiler Room</b>	
	<b>Stairs</b>						<b>Elevator Shaft</b>	

DATE	CONDITION OF WORK—REMARKS
12/4/30	3 <sup>rd</sup> insp. Ext. Area for Stueco Plastering of Dwg. over old rustic. O.K. A.W. Campbell
	<p style="text-align: center;">COMPLETED AND O.K.</p> <p style="text-align: right;">INSPECTOR</p>