

CITY OF SACRAMENTO

CERTIFICATE OF OCCUPANCY

This Building, the address of which is 1708 59th Street,
Sacramento, California, is hereby classified as a Group B-1 Occupancy, to wit:
Tire Repair Addition, and is of Type III

Construction as defined in the Sacramento City Building Code. It has been constructed and completed in accordance with the requirements of the Sacramento City Building Code and, where applicable, with the requirements of the State Laws.

Therefore, as of this date December 7, 1994, it is hereby Certified for the Occupancy described above and may be occupied.

PERMIT NO.: 94-4111-C

OWNER: SMUD

DBA: Smud Tire Repair

Post in a 1,570 Sq. Ft.

Conspicuous Place

(over)

D.T. SULLIVAN, SUPERINTENDENT
Building Inspections Division

by: *[Signature]*
Bearsley Building Inspector