

**BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD**

**TYPE BUILDINGS**

*File*

<b>PERMIT NO.</b>					
No Permit	<b>LOCATION</b>	2347 - 16th Avenue			
<b>DATE</b>	<b>PURPOSE</b>	Wreck building			
	<b>OWNER</b>	Stella Gregson Box 100, Power Inn Road			
<b>ZONE</b>	<b>ARCH'T</b>	Florin, California			
	<b>CONT'R</b>				
<b>VAL.</b>	<b>STORIES</b>	<b>ROOMS</b>	<b>APTS.</b>	<b>SIZE</b>	
<b>INSP.</b>	<b>DATE</b>	<b>BLDG. TYPE</b>	<b>OCCUPANCY GROUP</b>	<b>PHONE (O) (C)</b>	
<b>FORM</b>					
<b>JOIST</b>		Condemned by Building Division			
<b>FRAME</b>					
<b>SHEET ROCK</b>					
<b>FINAL</b>	5-4-64	Fuller			

DATE	SPECIAL CONDITIONS OF WORK — REMARKS
COMPLETE AND OK	INSPECTOR