

## BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

## TYPE BUILDINGS

PERMIT NO. <i>B-70-175</i>	LOCATION <i>4841-B-20</i>			
DATE <i>3/3/42</i>	PURPOSE <i>Erect new dwlg &amp; gar</i>			
ZONE <i>2-Fam.</i>	OWNER <i>John Termaugh</i>			
	ARCH'T. <i>Deane</i>			
	CONTR. <i>Deane</i>			
VAL <i>3000</i>	STORIES <i>1</i>	ROOMS <i>1</i>	APTS.	SIZE
LIGHT SHAFTS	ELEVATOR SHAFTS	<i>Area</i>		
VENT SHAFTS	BOILER ROOMS	<i>840<sup>sq</sup></i>		
OWNER'S INSPECTOR	SPRINKLER SYSTEM	<i>@ 30%</i>		
LATH	GAS VENTS			
FIRE ESCAPES	CHIMNEYS			
STAND PIPES	SKYLIGHTS			

DATE	CONDITION OF WORK—REMARKS	
8/15-42	18'	Lump Formed OK Under
4/20-42	2	" " Frame OK Under
5/10-42	3	" " Last Job. Under
D/nd-42	4	" " Finished Under

COMPLETE  
AND O. K.

INSPECTOR