

R-64  
F34

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

**TYPE BUILDINGS \$3.00**

<b>PERMIT NO.</b> D-4226	<b>LOCATION</b> 517-41 St.	<b>A-1</b>
<b>DATE</b> Dec. 14, 59	<b>PURPOSE</b> Replace garage Windows & siding	
<b>ZONE</b> R-1	<b>OWNER</b> E. Butler Jr.	<b>ARCH'T</b>
	<b>CONT'R</b> 517-41 st.	GL 1-4886

<b>VAL.</b> \$400.	<b>STORIES</b>	<b>ROOMS</b>	<b>APTS.</b>	<b>SIZE</b>
--------------------	----------------	--------------	--------------	-------------

<b>INSP.</b>	<b>DATE</b>	<b>INSPECTOR</b>
<b>FORM</b>		
<b>JOIST</b>		
<b>FRAME</b>		
<b>LATH</b>		
<b>FINAL</b>	3-9-60	Shumway

DATE	SPECIAL CONDITIONS OF WORK—REMARKS
	<b>COMPLETE AND OK</b> <span style="float: right;"><b>INSPECTOR</b></span>