

## BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

## TYPE BUILDINGS

PERMIT NO. <i>B-24244</i>	LOCATION <i>1510 <del>1511</del> Street</i>
DATE <i>1-17-49</i>	PURPOSE <i>Repair garage bldg</i>
ZONE	OWNER <i>Wenderson &amp; Bender</i>
	ARCH'T.
	CONTR. <i>Frank Maloney</i>

VAL <i>\$6000</i>	STORIES	ROOMS	APTS.	SIZE
-------------------	---------	-------	-------	------

LIGHT SHAFTS		ELEVATOR SHAFTS	
VENT SHAFTS		BOILER ROOMS	
OWNER'S INSPECTOR		SPRINKLER SYSTEM	
LATH		GAS VENTS	
FIRE ESCAPES		CHIMNEYS	
STAND PIPES		SKYLIGHTS	

DATE	CONDITION OF WORK—REMARKS
2/17/29	Frame Insp. (rebuilding trusses & rear wall) D. E. Buckius
	COMPLETE AND O. K. <span style="float: right;">INSPECTOR</span>