

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-2425</i>	LOCATION <i>932-50th Street</i>			
DATE <i>2/10/39</i>	PURPOSE <i>New build</i>			
ZONE	OWNER <i>R. A. Blenheim</i>			
	ARCH'T.			
	CONTR. <i>Owner</i>			
VAL. <i>3500⁰⁰</i>	STORIES <i>1</i>	ROOMS <i>5</i>	APTS.	SIZE
LIGHT SHAFTS		ELEVATOR SHAFTS	<i>area</i>	
VENT SHAFTS		BOILER ROOMS	<i>940⁰⁰</i>	
OWNER'S INSPECTOR		SPRINKLER SYSTEM		
LATH		GAS VENTS		
FIRE ESCAPES		CHIMNEYS		
STAND PIPES		SKYLIGHTS		

DATE	CONDITION OF WORK-REMARKS
2/15-39	1 st Insp Forms on Rectifier
4/10-39	2 nd " Forms " Rectifier
4/19-39	3 rd Insp Lub Oil Int of Rectifier
	<div style="display: flex; justify-content: space-between;"> COMPLETE AND O. K. INSPECTOR </div>

