

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B. 5297</i>	LOCATION <i>2616 - 18th St.</i>			
DATE <i>4/15/40</i>	PURPOSE <i>General repairs - dwg.</i>			
ZONE	OWNER <i>Joseph Bordessa J.</i>			
	ARCH'T. <i>Pacific Roof Insuf. Co.</i>			
	CON'TR. <i>Pacific Roof Insuf. Co.</i>			
VAL. <i>1650⁰⁰</i>	STORIES	ROOMS	APTS.	SIZE
LIGHT SHAFTS		ELEVATOR SHAFTS		
VENT SHAFTS		BOILER ROOMS		
OWNER'S INSPECTOR		SPRINKLER SYSTEM		
LATH		GAS VENTS		
FIRE ESCAPES		CHIMNEYS		
STAND PIPES		SKYLIGHTS		

DATE	CONDITION OF WORK—REMARKS
5/16/45	2 ND MSP. Frame for 2 ND Stone Addition to old dwelling OK R. W. Campbell
	<p data-bbox="319 833 437 875">COMPLETE AND O. K.</p> <p data-bbox="1105 854 1231 875">INSPECTOR</p>

