

BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-11025</i>	LOCATION <i>1300 - 39th St.</i>
DATE <i>1/9/43</i>	PURPOSE <i>Repairs to dwlg</i>
ZONE	OWNER <i>Hyberg</i>
	ARCH'T.
	CONTR. <i>Wm LaLue</i>

VAL. *25000*

STORIES

ROOMS

APTS.

SIZE

LIGHT SHAFTS		ELEVATOR SHAFTS	
VENT SHAFTS		BOILER ROOMS	
OWNER'S INSPECTOR		SPRINKLER SYSTEM	
LATH		GAS VENTS	
FIRE ESCAPES		CHIMNEYS	
STAND PIPES		SKYLIGHTS	

DATE	CONDITION OF WORK-REMARKS
1/11/43	Made inspection of repairs to cement floor
	+ foundation for storage room adj. Garage
	Contractor changed garage doors to over-
	head type and made minor repairs
	O.K. A.W. Campbell
	COMPLETE AND O. K. INSPECTOR