

## BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

## TYPE BUILDINGS

PERMIT No. a 243	LOCATION 1201 - 18 <sup>th</sup> St.
DATE 12/3/32	PURPOSE Remodelling of 1st floor
ZONE 3-2	OWNER Albert Brumma
	ARCH'T Albert Brumma
	CONT-R Albert Brumma
	PHONES

VAL. 300 —	STORIES	ROOMS	APTS.	SIZE
Light Shafts		Elevator Shafts		
Vent Shafts		Boiler Rooms		
Owner's Inspector		Sprinkler System		
Lath		Gas Vents		
Fire Escapes		Chimneys		
Stand Pipes		Skylights		

DATE	CONDITION OF WORK—REMARKS
12/8/32	Made Partial Insp. of work being done to install stair in basement of 7 Story Apt House. Construction now proceeding for cement floor. Going to install 5- 3" steel columns and 8" I Beam Leds in center. R.W. Campbell
12/14/32	1 <sup>st</sup> / HSP Form for Piers and Retaining Walls. <sup>OK</sup> R.W. Campbell
12/23/32	2 <sup>nd</sup> / HSP Form. Steel I Beam Columns in place. <sup>OK</sup> R.W. Campbell
12/27/32	3 <sup>rd</sup> / HSP. Int. Metal Lath & Plaster Walls & Ceiling for Stairs. <sup>OK</sup> R.W. Campbell
1/23/33	4 <sup>th</sup> / HSP. Above work completed. <sup>OK</sup> R.W. Campbell
1/23/33	COMPLETE AND O.K. <i>Alden W. Campbell</i> INSPECTOR