

**BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD**

**TYPE BUILDINGS**

<b>PERMIT NO.</b> <i>B-24707</i> <b>DATE</b> <i>3-7-49</i> <b>ZONE</b> <i>Noch</i>	<b>LOCATION</b> <i>1020 - I street</i>
	<b>PURPOSE</b> <i>Partitions</i>
	<b>OWNER</b> <i>Safety Systems</i>
	<b>ARCH'T.</b>
	<b>CONTR.</b> <i>Owner</i>

<b>VAL.</b> <i>140</i>	<b>STORIES</b>	<b>ROOMS</b>	<b>APTS.</b>	<b>SIZE</b>
------------------------	----------------	--------------	--------------	-------------

<b>LIGHT SHAFTS</b>		<b>ELEVATOR SHAFTS</b>	
<b>VENT SHAFTS</b>		<b>BOILER ROOMS</b>	
<b>OWNER'S INSPECTOR</b>		<b>SPRINKLER SYSTEM</b>	
<b>LATH</b>		<b>GAS VENTS</b>	
<b>FIRE ESCAPES</b>		<b>CHIMNEYS</b>	
<b>STAND PIPES</b>		<b>SKYLIGHTS</b>	

DATE	CONDITION OF WORK—REMARKS
5/2/49	No Insp. Called For O.E. Buckins (Wood Frame Const. Wrong in Fire Zone I)
	COMPLETE AND O. K. <span style="float: right;">INSPECTOR</span>