

BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD

\$13.00

TYPE BUILDINGS

PERMIT NO. F-5919	LOCATION 3449 - 33rd Street A-1				
DATE Nov. 21-67	PURPOSE Repair dwlg. per list from Housing				
OWNER	Clarence Spragg 5421 -70th Street				
ZONE R-1	ARCH'T				
	CONTR	Onwer	Same	456-6835	
VAL. \$1,500.	STORIES	ROOMS	APTS.	SIZE	
INSP.	DATE	BLDG. TYPE	V no hr	OCCUPANCY GROUP	PHONE (O) (C)
FORM	3-12-68	Brick		I-1	
JOIST	6-25-67	Steel			
FRAME					
SHEET ROCK	1-23-68	Bulla			
FINAL	2-13-69				G. Harmon

DATE	SPECIAL CONDITIONS OF WORK — REMARKS
12/13/66	OK Beam, Base patch only Ripin
6-22-67	PT beam - Not ready Crest
7-3-67	Lacked, unable to get job card Ribs
12-20-67	P.T. not enough nails - Ribs
12-21-67	PT SR. Lacked up Ribs
2-2-68	PT beam - Not ready Bull
2-1-68	PT beam - Base in steps Hammer not over
	COMPLETE AND OK INSPECTOR

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32
33
34
35
36
37
38
39
40
41
42
43
44
45
46
47
48
49
50
51
52
53
54
55
56
57
58
59
60
61
62
63
64
65
66
67
68
69
70
71
72
73
74
75
76
77
78
79
80
81
82
83
84
85
86
87
88
89
90
91
92
93
94
95
96
97
98
99
100