

BUILDING DIVISION--BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-10,180</i>	LOCATION <i>5007-B-2A</i>
DATE <i>3/30/4</i>	PURPOSE <i>Erection new dwlg - gar.</i>
ZONE <i>2 Jan</i>	OWNER <i>John Fernandez</i>
	ARCH'T. <i>O'Connor</i>
	CONTR. <i>O'Connor</i>

VAL <i>300</i>	STORIES <i>1</i>	ROOMS <i>5</i>	APTS.	SIZE
-------------------	---------------------	-------------------	-------	------

LIGHT SHAFTS		ELEVATOR SHAFTS	<i>area</i>
VENT SHAFTS		BOILER ROOMS	<i>840'1</i>
OWNER'S INSPECTOR		SPRINKLER SYSTEM	<i>@ 350</i>
LATH		GAS VENTS	
FIRE ESCAPES		CHIMNEYS	
STAND PIPES		SKYLIGHTS	

DATE	CONDITION OF WORK—REMARKS	
4-10-42	18	Lump Formed at Point
5/11/42	2	" Formed at Point
10/19/42	6	" Last West, Point
1/15/42	4	" Finaldelf in Point

COMPLETE
AND O. K.

INSPECTOR