

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

| | | | | |
|-------------------------------|--|------------------|-------|------|
| PERMIT NO. B-10,489 | LOCATION 904 - 33rd St. | | | |
| DATE 6/25/42 | PURPOSE Repair & raise roof | | | |
| ZONE | OWNER E. W. Linnwaldt | | | |
| | ARCH'T. | | | |
| | CONT'R. Owner | | | |
| VAL. 300⁰⁰ | STORIES | ROOMS | APTS. | SIZE |
| LIGHT SHAFTS | | ELEVATOR SHAFTS | | |
| VENT SHAFTS | | BOILER ROOMS | | |
| OWNER'S INSPECTOR | | SPRINKLER SYSTEM | | |
| LATH | | GAS VENTS | | |
| FIRE ESCAPES | | CHIMNEYS | | |
| STAND PIPES | | SKYLIGHTS | | |

| DATE | CONDITION OF WORK-REMARKS |
|------|--|
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | <p data-bbox="295 866 417 902">COMPLETE AND O. K.</p> <p data-bbox="1107 881 1240 902">INSPECTOR</p> |