

**BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD**

**TYPE VII BUILDINGS**

<b>PERMIT NO.</b> 6579	<b>LOCATION</b> 1467-48th		
<b>DATE</b> 7/15/31	<b>PURPOSE</b> Repair	<b>ROOMS</b>	<b>APTS.</b>
<b>ZONE</b>	<b>OWNER</b> Gus Gabrielli	<b>PHONE</b>	
	<b>ARCH'T</b>		
	<b>CONT'R</b> Stan K... Co		
	<b>VAL.</b> 175-	<b>STORIES</b>	<b>SIZE</b>

FOUNDATION	STORY	BSMT	1	2	3	ROOF		
Ex Wall	Joists						Chimneys	Cement Tests
	Beams and Girders						Fire Place	
Int Wall	Studs and Columns						Gas Water Heater	
	Bridging Fire Stops						Heater Closet	
Piers	Fire Escape Stand Pipes						Furnace	Window Courts
	Metal Lath						Boiler Room	
	Stairs						Elevator Shaft	



DATE	CONDITION OF WORK—REMARKS
7/17/31	Re Roofing of Dairy with Composition Shingles completed O.K.
	W. Campbell
	COMPLETED AND O.K. <span style="float: right;">INSPECTOR.</span>

