BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

# TYPE VII BUILDINGS

| PERMIT NO. | LOCATION | | |
|---|---|---|---|
| 2723 | | 1349-58 | |
| DATE | PURPOSE Rebuild Barn - Blk Lock Yard | ROOMS | APTS. |
| ISSUED | OWNER Jeanette Mujai | | PHONE |
| ZONE | ARCHT. | | |
| MAY 22 1928 | CONTR. | | |
| SACRAMENTO BUILDING DIVISION | EVAL. 100 | STORIES | SIZE |

| FOUNDATION | STORY | BSMT | 1 | 2 | 3 | ROOF | | | |
|---|---|---|---|---|---|---|---|---|---|
| Ex Wall | Joists | | | | | | Chimneys | | Cement Tests |
| | Beams and Girders | | | | | | Fire Place | | |
| Int Wall | Studs and Columns | | | | | | Gas Water Heater | | |
| | Bridging Fire Stops | | | | | | Heater Closet | | |
| | Fire Escape Stand Pipes | | | | | | Furnace | | Window Courts |
| Piers | Metal Lath | | | | | | Boiler Room | | |
| | Stairs | | | | | | Elevator Shaft | | |

| DATE | CONDITION OF WORK—REMARKS |
| --- | --- |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | COMPLETED AND O. K. INSPECTOR |