

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>A-4695</i>	LOCATION <i>416 San Antonio</i>			
DATE <i>8/18/36</i>	PURPOSE <i>Erect new dwlg garage</i>			
ZONE <i>2-Fam</i>	OWNER <i>Plein Realty Co.</i>			
	ARCH'T. <i>Owner</i>			
	CONT'R. <i>807-JCA</i>			
VAL. <i>3500<sup>00</sup></i>	STORIES <i>1</i>	ROOMS <i>5</i>	APTS.	SIZE

LIGHT SHAFTS	ELEVATOR SHAFTS	<i>1000<sup>00</sup></i>
VENT SHAFTS	BOILER ROOMS	<i>@ 350</i>
OWNER'S INSPECTOR	SPRINKLER SYSTEM	
LATH	GAS VENTS	
FIRE ESCAPES	CHIMNEYS	
STAND PIPES	SKYLIGHTS	

DATE	CONDITION OF WORK--REMARKS
8/21/36	1 <sup>st</sup> / HSP. Forms in place <sup>of</sup> A W Campbell
9-7-0	2 <sup>nd</sup> " " Frame of Ruiters
9-16	3 <sup>rd</sup> " " Job Ext Lark Ruiters
	<div style="display: flex; justify-content: space-between;"> <span data-bbox="319 802 452 844">COMPLETE AND O. K.</span> <span data-bbox="1172 823 1313 844">INSPECTOR</span> </div>