

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE VII BUILDINGS

PERMIT NO. 5840	LOCATION 3617-15 St		
DATE 4/3/30	PURPOSE Alteration	ROOMS ✓ Rm	APTS. ✓ Apt
ZONE Dwelling	OWNER H.A. Campbell	PHONE	
	ARCH'T		
	CONT'R D. Campbell		
	VAL.	STORIES	SIZE

FOUNDATION	STORY	BSMT	1	2	3	ROOF		
EX WALL	Joints						Chimneys	Cement Tests
	Beams and Girders						Fire Place	
Int Wall	Studs and Columns						Gas Water Heater	
	Bridging Fire Stops						Heater Closet	
Piers	Fire Escape Stand Pipes						Furnace	Window Courts
	Metal Lath						Boiler Room	
	Stairs						Elevator Shaft	

DATE	CONDITION OF WORK—REMARKS
7/4/30	Made preliminary inspection of Repairs to Driv. Re Roofed with Composition Shingles.
	Addition on rear not yet started. A.H. installed
7/27/30	Composition Roof Install OK R.H. Rutter
12/17/30	1 Imp. Foundation OK R.H. Rutter
7/25/30	2 Imp. Frame OK R.H. Rutter
11/1/30	3 " Int Saph OK R.H. Rutter
3/19/30	4 th Imp. Finished + OK R.H. Rutter
	Street cleaned up
	<p style="text-align: center;">COMPLETED AND O.K.</p> <p style="text-align: center; font-size: 2em;">R.H. Rutter</p> <p style="text-align: right;">INSPECTOR</p>