

BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <b>8001</b>	LOCATION <b>1910 W. Main</b>
DATE <b>5/7/31</b>	PURPOSE <b>Revol of install from Gen. Reg</b>
ZONE <b>Gen Com</b>	OWNER <b>Gen. Shadle</b>
	ARCH'T <b>[Signature]</b>
	CONT-R <b>[Signature]</b>
	PHONES <b>[Blank]</b>

VAL. <b>3rd</b>	STORIES	ROOMS	APTS.	SIZE
--------------------	---------	-------	-------	------

Light Shafts		Elevator Shafts	
Vent Shafts		Boiler Rooms	
Owner's Inspector		Sprinkler System	
Lath		Gas Vents	
Fire Escapes		Chimneys	
Stand Pipes		Skylights	

DATE	CONDITION OF WORK-REMARKS
3/19/31	<p>1<sup>st</sup>/NSP. Forms in place. In Home on rear of lot  raised up will be 2' below floor joists clearance.  Notified Owner to remove all timbers obstructing by  Terminals and Dry Rot. Note for enough to demur.</p> <p style="text-align: right;">M. Campbell</p>
COMPLETE AND O.K.	INSPECTOR