

R 3410 F 159

**BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD**

\$5.00

**TYPE BUILDINGS**

<b>PERMIT NO.</b>					
G-1500	<b>LOCATION</b> 1288 - Nevis Court A-3 (33)				
<b>DATE</b>	<b>PURPOSE</b> Repair rot damage in shower in dwelling.				
Sept-18-68	<b>OWNER</b> Howard Lee		Same		
<b>ZONE</b>	<b>ARCH'T</b>				
R-1	<b>CONTR</b> Atox Termite Control 5831 - Rosebud				
<b>VAL.</b> \$200,		<b>STORIES</b>	<b>ROOMS</b>	<b>APTS.</b>	<b>/Lane</b> <b>SIZE</b>
<b>INSP.</b>	<b>DATE</b>	<b>BLDG. TYPE</b>		<b>OCCUPANCY GROUP</b>	<b>PHONE (O) (C)</b>
<b>FORM</b>					
<b>JOIST</b>					
<b>FRAME SHEET ROCK</b>	9-19-68	Fuller			
<b>FINAL</b>	3-21-69	M. Callaway			

DATE	SPECIAL CONDITIONS OF WORK — REMARKS
COMPLETE AND OK	INSPECTOR